

Municipal Waste Landfill Inspection Report

Permit Number	100022	EPA ID Number	----
Facility Name	CHRIN BROS SANI LDFL	Operator Name	CHRIN BROS INC
Address	1225 INDUSTRIAL DR	Address	1225 INDUSTRIAL DR
City/State/Zip	EASTON PA 18042-6829	City/State/Zip	EASTON PA 18042-6829
Municipality	Williams Township	County	----
Responsible Official	Gregory Chrin	Title	Owner/ Operator
Person Interviewed	Joe Klobusicky	Title	Environmental Manager
		Telephone #	1
Lead Inspector	EDWARD MCNULTY	Title	SLD WSTE SPCST
Additional Personnel	MAATTHEW GLOGOWSKI	Title	ENV ENGR
Site ID	238053	Client ID	42952
PF ID	240650	SF ID	201820
Inspection Start Date	04/16/2025 07:45 AM	Inspection End Date	04/16/2025 11:22 AM
Inspection Type	RTNC - Routine/Complete Inspection	Inspection Result	No Violations Noted
Permit Expiration Date	01/06/2030	Days/Week Operated	6
		Max. Daily Volume	2000 Tons/Day

Check Lists

Municipal Waste Landfill (0131)			
Status	Requirement	Chapter Citation	Line Item
GENERAL PROVISIONS			
No Violation	Required insurance in effect	271.371	1
	(expiration date) 12/01/2025		1A

No Violation	Operation in accordance with approved plans and permit.	273.201(c)(2)	2
No Violation	Operation within permit boundaries (vertical and horizontal).	273.201(c)(2)	3
No Violation	Disposal Timing and sequence as per Section 273.112(1).	273.201(c)(2)	4
No Violation	No unapproved wastes or liquids.	273.201(d)-(m)	5
No Violation	Isolation distances are adhered to.	273.202(a)	6
No Violation	Facilities certification requirements followed.	273.203(a), (b)	7
No Violation	Written Department approval of new construction prior to waste disposal.	273.203(c)	8
DAILY OPERATIONS			
No Violation	Proper signs posted.	273.211(a)	9
No Violation	Site perimeter clearly marked and grid coordinate system in use.	273.211(b)-(d)	10
No Violation	Proper barriers installed around site and access controlled when attendant not present.	273.212(a)-(i)	11
No Violation	Access roads maintained and negotiable by collection vehicles.	273.213(a)-(i)	12
No Violation	Approved means of measuring and inspected waste utilized. Remark: Chrin's weight scale was last calibrated 10/29/25. Chrin recorded 86 overweight trucks in April.	273.214(a), (b)	13
No Violation	Adequate equipment on-site and stand-by equipment available.	273.215(a), (b)	14
No Violation	Vehicles directed promptly to unloading area and promptly unloaded.	273.216(a), (b)	15
No Violation	Solid waste spread and compacted as approved by Department as part of permit.	273.216(c)	16

No Violation	Operator implements fugitive air contaminant control/measures and prevents and controls air pollution including no exceeding of ambient air quality standards, no open burning, and minimizing generation of fugitive dust emissions from facility.	273.217(a)	17
No Violation	Operator complies with Air Quality Plan approval and Air quality Operating Permit.	273.217(b)	18
No Violation	Operator does not cause or allow attraction, harborage, or breeding of vector.	273.218(a)	19
No Violation	Operator implements nuisance minimization and control plan.	273.218(b)(1)	20
No Violation	Operator performs regular, frequent, and comprehensive site inspections to reduce potential for offsite odors.	273.218(b)(2)	21
No Violation	Operator promptly addresses and correct problems and deficiencies discovered during inspections.	273.218(b)(3)	22
No Violation	Operator implements nuisance minimization and control plan to minimize and control other conditions harmful to the environment or public health, or which create safety hazards, odors, dirt, noise, unsightliness and other public nuisances. Remark: Chrin's nuisance load log and patrol log were reviewed. Patrols were being conducted in accordance with their nuisance minimization and control plan. No nuisance loads were recorded since the last inspection.	273.218(c)	23
No Violation	Operator does not receive solid waste at a landfill in excess of the maximum or average daily volume approved in the permit. Remark: Daily incoming volumes were reviewed for March and April 2025. The highest incoming tonnage for this period was 762.4 tons on 4/28/25.	273.221(a)	24

No Violation	Operator implements radiation protection action plan.	273.223(a)	25
No Violation	Operator monitors incoming waste in accordance with Department's guidance or in a manner at least as protective of the environment, facility staff and public health and safety. Remark: Daily Radiation source checks were reviewed for the period of 3/21/25 through 4/16/25. Chrin recorded one radiation hit, 4/29/25 Lu-177 origin: Holland Disposal (MSW route)	273.223(b)	26
No Violation	Radiation detector elements shall be as close as practical to wasteload and in appropriate geometry to monitor the waste.	273.223(c)	27
No Violation	Operator has portable radiation monitors capable of determining the dose rate and presence of contamination of a vehicle that has caused an alarm. Upon exceedance of alarm level, a radiological survey of the vehicle is performed.	273.223(d)	28
No Violation	Operator notifies Department immediately and isolates vehicle when radiation dose rates are exceeded.	273.223(e)	29
No Violation	Monitoring equipment is calibrated at frequency specified by manufacturer, but not less than once a year.	273.223(f)	30
No Violation	If radioactive material is detected, vehicle containing material shall not leave facility without written Department approval and an authorized federal Department of Transportation exemption form.	273.223(g)	31
No Violation	Uniform cover of the approved daily cover material is placed on exposed solid waste at the end of each working day or at the end of every 24 hours, whichever interval is less.	273.232(a)	32

No Violation	If intermediate cover requires revegetation, it is established within 30 days.	273.233(e)	33
No Violation	Slopes constructed during daily landfilling and intermediate cover activities may not exceed 50 percent.	273.233(f)	34
No Violation	Operator does not cause or allow waste pollution within or outside the site from operation of the facility.	273.241(a)-(c)	35
Not Applicable	Operator has restored or replaced adversely affected water supply with an alternative source of like quantity and quality.	273.245(a)	36
Not Applicable	Temporary water supply is provided within 48 hours.	273.245(b)	37
Not Applicable	Permanent water supply is provided within 90 days.	273.245(c)	38
No Violation	No waste 15 feet of inside top of the lined perimeter berm.	273.252(e)	39
No Violation	Lined perimeter berm 4 ft. high constructed and maintained along edge of the lined disposal area.	273.252(f)	40
No Violation	Edge of liner clearly marked.	273.252(g)	41
Not Applicable	Alternate leachate recirculation method may be used if approved if one of the liner systems is a composite liner.	273.274(b)	42
No Violation	Underground pipes used to transport leachate to leachate storage impoundments or tanks equipped with secondary containment or comply with 245.445.	273.275(g)	43
Not Applicable	Operator isolates coal seams, coal outcrops and coal refuse from waste deposits to prevent combustion of waste and damage to liner.	273.291(a)	44
Not Applicable	Mine openings within site sealed as approved by Department.	273.291(b)	45

Not Applicable	Operator implements plan for controlling potential damage from subsidence submitted and approved under 273.120.	273.291(c)	46
No Violation	Landfill designed, constructed, maintained and operated to prevent and minimize potential for fire, explosion, or release of solid waste constituents into air, water, or soil of the Commonwealth.	273.301	47
No Violation	Emergency equipment including portable fire extinguishers, fire control equipment, spill control equipment, and decontamination equipment available. For fire equipment requiring water, facility has a water supply of or adequate quantity and pressure to supply the equipment.	273.302(a)	48
No Violation	Emergency equipment tested and maintained.	273.302(c)	49
No Violation	Adequate space maintained to allow unobstructed movement of emergency personnel and equipment.	273.302(d)	50
No Violation	Litter controlled/collected and barriers/fences in place.	273.220(a)-(c)	51
COVER/SLOPES/REVEGETATION			
No Violation	Daily/intermediate cover meets performance and design requirements. Remark:	273.232(b), 273.233(b), (c)	52
No Violation	Minimum 5 day supply of daily and intermediate cover maintained on-site.	273.232(c) & 273.233(d)	53
No Violation	Intermediate cover applied within time limits.	273.233(a)	54
No Violation	Intermediate slopes do not exceed 50%.	273.232(d)	55
No Violation	Cap placed over entire surface of final lift meets performance standards.	273.234(a)(1)	56
No Violation	Final cover meets performance and design requirements; applied within time limits.	273.234(b)-(e)	57

No Violation	Final slopes stable and erosion controlled.	273.234(f)	58
No Violation	Final slopes graded 3-15% or terraced to 33% as approved.	273.234(g)	59
No Violation	Minimum revegetation and successful revegetation requirements adhered to.	273.235(a)-(e) 273.236(a), (b)	& 60
WATER QUALITY PROTECTION			
No Violation	Surface and groundwater treatment facilities properly operated and maintained.	273.241(b)	61
No Violation	Surface water percolation minimized/prevented.	273.242(b)(1) 273.234(e)(4)	& 62
No Violation	Soil erosion and sedimentation controls designed and implemented as per approved plans; gullies over nine inches repaired. Remark:	273.242(a)-(c)	63
No Violation	Sedimentation ponds and discharge structures designed, constructed, operated, and maintained in accordance with Chapters 273, 102, and 105.	273.243(a)-(g) & 273.244	64
LINER SYSTEM			
No Violation	Liner system designed, constructed, operated, and maintained when required.	273.251(a), (b)	65
No Violation	Edge of liner requirements adhered to (i.e., no waste within 25 feet of adjacent liner, 4 feet high lined berm, to prevent lateral escape of leachate, adequate spacing on inside of berm to collect stormwater and sediment).	273.252(d)	66
No Violation	Leachate detection zone monitored weekly.	273.255(c)	67
No Violation	Protective cover protects primary liner and leachate collection system and allows free flow of leachate into the collection system.	273.257(a)	68
No Violation	Protective cover meets minimum requirements and at least 18 inches thick.	273.257(b)	69

No Violation	Leachate collection system within protective cover meets minimum requirements.	273.258(a), (b)	70
No Violation	Barrier designed, constructed and maintained as required to prevent lateral migration of leachate off-site in surface mined areas.	273.259(a)-(d)	71
No Violation	8 feet of select waste placed over protective cover.	273.260	73
LEACHATE TREATMENT			
No Violation	Leachate collected and handled through Department approved method(s).	273.272(a)-(c)	74
Not Applicable	Leachate transportation requirements adhered to.	273.273(a)-(c)	75
No Violation	Cessation of site operation if alternate leachate handling not available.	273.273(d)	76
Not Applicable	Leachate treatment system permitted and fully operational at least 3 years before closure.	273.273(e)	77
Not Applicable	Leachate recirculation in accordance with regulations.	273.274(1)-(4)	78
No Violation	Leachate collection and storage systems on-site have capacity of 30 days or 250,000 gallons, whichever is greater.	273.275(a)-(f)	79
No Violation	Leachate flow rate measured daily; analyzed quarterly. Remark: Monthly leachate flow for March 2025 was 912,162 gallons. 29,425 gallons per day.	273.276(a)-(b)	80
No Violation	Department notified when remedial action(s) required.	273.277(1)-(4)	81
WATER QUALITY MONITORING			
No Violation	Approved monitoring system installed and maintained.	273.281(a), (b) & 273.283	82
No Violation	Quarterly and annual monitoring requirements adhered to and results submitted Department within time constraints.	273.284 & 273.285	83

No Violation	Groundwater assessment plan submitted and implement as required.	273.286(a)-(g)	84
No Violation	Groundwater abatement plan submitted and implemented as required.	273.287(a)-(f)	85
RECORDKEEPING AND REPORTING			
No Violation	Operational records maintained, available and submitted as required.	273.288 & 273.311-273.313	86
No Violation	Daily Operational Records kept in accordance with regulations for the life of the facility bond or longer if necessary.	273.311(d)	87
No Violation	Operator submits quarterly operation report.	273.312	88
No Violation	Operator submits annual operation report with fee.	273.313	89
MINERALS AND GAS			
No Violation	Gas venting and monitoring in accordance with approved plans.	273.292(a)-(d)	90
No Violation	Combustible gas levels not exceeded.	273.292(e)	91
No Violation	Forced gas venting if required.	273.292(f)	92
No Violation	Gas recovery conducted as per approved plan and §273.293, including annual analysis.	273.293(a), (b)	93
EMERGENCY PROCEDURES			
No Violation	Contingency plan implemented if there is an emergency.	273.303(a)-(c)	94
RECYCLING			
No Violation	Operator shall salvage and recycle waste in accord with recycling plan. (273.196)	273.331(a)	95
No Violation	Salvaging and recycling controlled by operator and prevents interference within operations and prevents health hazardous nuisance.	273.331(b)	96
No Violation	Salvaged materials stored in an approved area or transported offsite.	273.331(c)	97

No Violation	Drop off center established for at least three recyclables.	273.332(a)	98
No Violation	Drop off center properly located, contains bins or containers, open at least 8 hours per week and 4 hours during evenings or weekends.	273.332(b), (c)	99
No Violation	Approved public notice of availability of drop off center availability is provided.	273.332(d)	100
No Violation	On or before January 15 each year, operator informs municipality in writing of weight and type of materials recycled previous year.	273.332(e)	101
SPECIAL HANDLING AND RESIDUAL WASTES			
No Violation	Special handling and residual wastes disposed with prior Department approval, and in accordance with permit and Chapter 273.	273.501	102
Not Applicable	Infectious waste disposal restrictions adhered to.	273.511(a)-(d)	103
Not Applicable	Chemotherapeutic waste disposal restrictions adhered to.	273.512	104
No Violation	Sewage sludge co-disposal and monofill requirements followed.	273.513	105
No Violation	Sewage sludge sampling requirements adhered to and sludge meets standards for control of pathogens, vectors, and odors.	273.513(c)	106
Not Applicable	Disposal of municipal waste incineration ash in landfill or landfill cell that meets Chapter 273 requirements.	273.514(a)	107
Not Applicable	Ash residue disposal in dedicated landfill or landfill cell unless co-disposal in accordance with Chapter 273 (including leachability treatment).	273.514(b)	108
Not Applicable	Ash residue covered immediately or as approved by the Department.	273.514(c)	109
BONDING AND INSURANCE			

No Violation	Bond filed with Department.	271.312	110
No Violation	Bond maintained in an amount and with 271.333(b) guarantees as required.		111
	Bond amount \$		111A
	Phased deposit due date		111B
No Violation	Proof of a commercial policy of liability 271.374 insurances submitted to the Department as specified by 271.374.		112
	Policy # GEC003617613		112A
	Insurer (company name) Greenwich Insurance Company		112B
	Expiration Date: 12/01/2025		112C

Comments

On April 16, 2025 the PA Department of Environmental Protection ("the Department") conducted a complete routine inspection at Chrin Bros. Sanitary Landfill ("Chrin"). Representing the Department was Ed McNulty (this inspector) and Matthew Glogowski, who joined the site tour for their own inspection. Representing Chrin was Joseph Klobusicky who provided a site tour and was interviewed on behalf of Chrin.

An odor patrol as conducted in the vicinity of Chrin after the site tour, a very slight gas odor was detected on Waltman Loop, and slight gas and garbage odors were detected at the end of Spring Valley Road.

Waste Hauler inspections were conducted at Chrin Landfill the morning of 4/16/25 beginning at 7:45 and ending at 12:00. Fifty-one waste hauler vehicles were inspected and violations were issued to eight vehicles. See attached waste hauler inspection reports.

The following Department personnel have entered the landfill since the last inspection on 3/21/25. A. Faulch on 4/16/25 and M. Kolessar on 4/16/25 E. McNulty on 4/16/25, and M. Glogowski on 4/16/25.

Roads inside the landfill were OK. Line odor misters were running on fences along the haul road.

The working face was in cell 9-A. Two loaders and one compactor were operating at the working face. Waste relocation was active. A pile of relocated waste was seen at the working face. Several pieces of wind blown litter were observed in trees and along fences near the working face. Joe K said a crew would be collecting the litter by the end of the day. Waste was being sprayed with water with deodorizer mixed in. An old camper trailer was delivered to the working face for disposal.

Final cap was being installed in cell 3-D and 3-E. A permit modification had been submitted that would allow Chrin to stage a small recycling transfer area in the area of cell 3-E for Chrin vehicles to store recycling in case other waste sites were closed.

Excavation was being performed in the eastern expansion area. No new construction of the MSE wall had been done since the last inspection but would resume soon.

Flare 3 was active, flare 4 was inactive, data from the flares was provided by Joe K. SCADA system to monitor flares was being set up.

Leachate pipes were being installed on Industrial Drive. Quarterly groundwater monitoring was ongoing.

Since the 3/21/25 inspection report was issued on 4/4/25, the Department received one odor complaint. Odor patrols were conducted by the Department on and 4/16/25.

Check List Comments

Line Item 13 - Approved means of measuring and inspected waste utilized.

Remark: Chrin's weight scale was last calibrated 10/29/25. Chrin recorded 86 overweight trucks in April.

Line Item 23 - Operator implements nuisance minimization and control plan to minimize and control other conditions harmful to the environment or public health, or which create safety hazards, odors, dirt, noise, unsightliness and other public nuisances.

Remark: Chrin's nuisance load log and patrol log were reviewed. Patrols were being conducted in accordance with their nuisance minimization and control plan. No nuisance loads were recorded since the last inspection.

Line Item 24 - Operator does not receive solid waste at a landfill in excess of the maximum or average daily volume approved in the permit.

Remark: Daily incoming volumes were reviewed for March and April 2025. The highest incoming tonnage for this period was 762.4 tons on 4/28/25.

Line Item 26 - Operator monitors incoming waste in accordance with Department's guidance or in a manner at least as protective of the environment, facility staff and public health and safety.

Remark: Daily Radiation source checks were reviewed for the period of 3/21/25 through 4/16/25. Chrin recorded one radiation hit, 4/29/25 Lu-177 origin: Holland Disposal (MSW route)

Line Item 80 - Leachate flow rate measured daily; analyzed quarterly.

Remark: Monthly leachate flow for March 2025 was 912,162 gallons. 29,425 gallons per day.

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed

Unable To Obtain Reason: Delivered via email

Date --/--/----

Inspector



Date 05/09/2025

Investigator: Ed Marking

Date: 4-16-25

CASE: Chrin

Weather Conditions: Temp 47°F, Winds 7 mph NNW, Humidity 48%

ODOR PATROL SURVEY

[illegible]

CHRIN ODOR COMPLAINT LOG (1225 Industrial Dr., Easton, PA 18042)

Date	Time	Address	Distance from Landfill (miles)	Weather Data (Allentown KABE) www.wunderground.com			Residence / Drive-by	Description / Notes	Gas Management Data					Date of Initial Response	Addressed in Insp Report Dated
				Skies	Temperature °F	Wind (out of)			Flare 1 (scfm)	Flare 3 (scfm)	Flare 4 (scfm)	PPL (scfm)	Total (scfm)		
01/17/25	9:19	unknown	unknown		28	East/Southeast 0-1 mph	Residence	Every morning for the past year+ between the hours of roughly 7am-10 am and in early evening hours my neighborhood has overwhelming smell of methane gas. The belief is this odor is off gassing form the Chrin landfill. This has been a noticeable problem for the past year or so at least. I have acute asthma and suffer lung irritation and burning as a result of this when exercising or working outside during periods when the odor is level is high. I fear a toxic situation exists.			2300		2300	01/21/25	01/21/25
01/20/25	8:33	Morgan Hill Rd., Easton	1.390		15	Northeast 0-2 mph	Residence	The dump smells terrible again.			2500		2500	01/21/25	01/21/25
02/10/25	2:30	Merion Ln., Easton	1.744		30	South 0-1mph	Residence	At about 2:30 in the morning the landfill stunk so bad that the smell came in through my open window.			2540		2540	02/14/25	02/19/25
02/26/25	16:13	Waltman Loop	0.943		53	South/southwest 0-1mph	Residence	Garbage and methane smell. At home.			2610		2610	03/11/25	03/21/25
04/03/25	10:44	Merion Ln., Easton	1.744		49	South 0-1mph	Residence	Smelled odor from Chrin. At 10:44 AM while leaving the house.		1900			1900	04/04/25	03/21/25
04/16/25	14:15	Pine Valley Ter., Easton	1.297		48	Southwest 2-5 mph	Residence	Smells like rotten egg gas. The odor has been getting more frequent. Encountered since 2:15 PM at home.		1800			1800		

2025	Daily	Total Week	Month Average	Day	Total Month	Total Quarter
April						
1	652.2		652.2	1	652.2	652.2
2	592.2		622.2	2	1,244.4	1,244.4
3	560.9		601.8	3	1,805.3	1,805.3
4	543.3		587.2	4	2,348.6	2,348.6
5	88.1		487.3	5	2,436.7	2,436.7
6		2,436.72			2,436.7	2,436.7
7	659.6		516.1	6	3,096.3	3,096.3
8	695.2		541.6	7	3,791.5	3,791.5
9	568.2		545.0	8	4,359.7	4,359.7
10	532.7		543.6	9	4,892.4	4,892.4
11	510.3		540.3	10	5,402.8	5,402.8
12	90.8		499.4	11	5,493.6	5,493.6
13		3,056.87			5,493.6	5,493.6
14	738.0		519.3	12	6,231.6	6,231.6
15	684.5		532.0	13	6,916.1	6,916.1
16	544.2		532.9	14	7,460.3	7,460.3
17	510.8		531.4	15	7,971.1	7,971.1
18	754.6		545.4	16	8,725.7	8,725.7
19	103.4		519.4	17	8,829.1	8,829.1
20		3,335.47			8,829.1	8,829.1
21	730.1		531.1	18	9,559.1	9,559.1
22	551.1		532.1	19	10,110.2	10,110.2
23	604.8		535.8	20	10,715.0	10,715.0
24	599.0		538.8	21	11,314.0	11,314.0
25	640.1		543.4	22	11,954.1	11,954.1
26	66.9		522.7	23	12,021.0	12,021.0
27		3,191.95			12,021.0	12,021.0
28	762.4		532.6	24	12,783.4	12,783.4
29	725.1		540.3	25	13,508.5	13,508.5
30	655.0		544.8	26	14,163.6	14,163.6
Month Total						
14,163.6						

Chrin Brothers Sanitary Landfill 2024 Leachate Flow Summary

Leachate

Reading Date	Month	Reading	Monthly Flow	Gallons Per Day	GPD Per Acre	Quarterly Flows		
						Flow	Gal/Day	GPD/Ac
12/31/2024	DEC	574,400	255,158					
1/31/2025	JAN	1,335,733	761,333	24,559	233			
2/28/2025	FEB	337,394	448,206	16,007	152			
3/31/2025	MAR	1,249,556	912,162	29,425	279	2,121,701	23,574	223
4/30/2025	APR	2,319,031	1,069,475	35,649	338			
5/31/2025	MAY	0		0	0			
6/30/2025	JUN	0		0	0	1,069,475	11,752	111
7/31/2025	JUL	0		0	0			
8/31/2025	AUG	0		0	0			
9/30/2025	SEP	0	0	0	0	0	0	0
10/31/2025	OCT	0	0	0	0			
11/30/2025	NOV	0		0	0			
12/31/2026	DEC	0	0	0	0	0	0	0
Total Yearly Flow				0	0			

meter reset

1. There are 105.6 acres of area contributing to the leachate flows, 30 acres of the old unlined landfill and 75.6 acres of lined landfill.
2. Chrin changed flowmeters and the sewer discharge location to MH-2 on April 7, 2014.

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH24137	Waste Hauler Name	AG CONSTRUCTION, LLC
Hauler Address	2510 CHESTNUT LN	Vehicle License	(PA) ZWP1530
City/State/Zip	EASTON PA 18040-7886	Vehicle VIN	JALE5W160R7300220
Driver Name	Arijanit Gjevuka	Vehicle Type	Truck,
Driver License No.	(PA) 29071094	Waste Type	Municipal Waste Loose
Inspector	AMY E FAULCH	Title	SLD WSTE SUPV
		eFACTS Client ID#	385771
Inspection Date	04/16/2025 11:29:01 AM	No. of Viols	4
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name	Chrin Bros. Sanitary Landfill	Site Location	Williams Township

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3
WASTE CONTAINMENT			

No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
No Violation	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
~~No Violation~~ AF Violations	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
~~Violations~~ AF No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10
TRUCK/TRACTOR SIGNAGE			
Violations	Complete business name and address sign on vehicle.	285.218(1)	11
Violations	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13
TRAILER SIGNAGE			

No Violation	Complete business name and address sign on vehicle.	285.218(1)	14
No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
Violations	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo # 1: Driver's side of vehicle.



Photo # 2: Driver's side cab door.



Photo # 3: Vehicle leaking from tailgate.



Photo # 4: Passenger's side of vehicle.



Photo # 5: Vehicle leaking from tailgate.



Photo # 6: Passenger's side cab door.



Photo # 7: Act 90 sticker on Driver's side cab door.

New and Outstanding Violations

25 Pa. Code 285.215(a) 213(c) *AF*

Line Item: ~~40~~ 7 *AF*

Comment: Vehicle was leaking from tailgate.

285.218(1)

Line Item: 11

Comment: There was no sign bearing the business name and address (city, state) on the vehicle.

285.218(2)

Line Item: 12

Comment: Vehicle did not have a sign bearing the type of waste being hauled, specifically "Municipal Waste".

25 Pa. Code 285.213(a)(1)(i)

Line Item: 17

Comment: Vehicle did not have a fire extinguisher.

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed

Unable To Obtain Reason: Declined signature.

Date --/--/----

Inspector



Date 04/16/2025

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH1521	Waste Hauler Name	BEATTY CONTRACTORS & WRECKERS, LTD.
Hauler Address	3361 GUN CLUB RD	Vehicle License	PA-AE77505
City/State/Zip	NAZARETH PA 18064-9723	Vehicle VIN	1M2P268C3SM022348
Driver Name	Beatty Russell, Jr	Vehicle Type	Rolloff Carrier,
Driver License No.	26564567	Waste Type	Municipal Waste Loose
Inspector	MICHAEL KOLESSAR	Title	ENVTL TRN
		eFACTS Client ID#	149240
Inspection Date	04/16/2025 08:35:00	No. of Viols	1
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name		Site Location	

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3

WASTE CONTAINMENT

No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
No Violation	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
No Violation	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10

TRUCK/TRACTOR SIGNAGE

No Violation	Complete business name and address sign on vehicle.	285.218(1)	11
Violations	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13

TRAILER SIGNAGE			
No Violation	Complete business name and address sign on vehicle.	285.218(1)	14
No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
No Violation	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo #1- Side of vehicle with no universal waste marking



Photo #2- Back of vehicle



Photo #3- Side of vehicle with no universal waste marking

New and Outstanding Violations

285.218(2)

Line Item: 12

Comment: No municipal waste marked on vehicle.

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed



Date 04/16/2025

Inspector



Date 04/16/2025

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH24302	Waste Hauler Name	CASELLA MAJOR ACCOUNT SERVICES, LLC
Hauler Address	25 GREENS HILL LN	Vehicle License	(NJ) XPFK15
City/State/Zip	RUTLAND VT 05701-3804	Vehicle VIN	JHHHDM2H4JK002676
Driver Name	Nicholas Lawrence Brewer	Vehicle Type	Rolloff Carrier,
Driver License No.	B73665907310902	Waste Type	Municipal Waste Loose
Inspector	EDWARD MCNULTY	Title	SLD WSTE SPCST
		eFACTS Client ID#	387209
Inspection Date	04/16/2025 08:43:44 AM	No. of Viols	3
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name		Site Location	

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3
WASTE CONTAINMENT			

~~Violations~~ <i>AF</i> No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
No Violation	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
~~No Violation~~ <i>AF</i> Violations	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10
TRUCK/TRACTOR SIGNAGE			
Violations	Complete business name and address sign on vehicle.	285.218(1)	11
Violations	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13
TRAILER SIGNAGE			
No Violation	Complete business name and address sign on vehicle.	285.218(1)	14

No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
No Violation	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo #



Photo #



Photo #



Photo #

New and Outstanding Violations

25 Pa. Code 285.211(a) 213(c) *AF*

Line Item: 4 7 *AF*

Comment: Waste container was steadily leaking fluid from the rear during inspection

285.218(1)

Line Item: 11

Comment: Vehicle lacks signage indicating business address

285.218(2)

Line Item: 12

Comment: Vehicle lacks signage indicating the type of waste being transported (municipal waste)

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed



Date 04/16/2025

Inspector



Date 04/16/2025

Corrections made by Amy Faulch, Solid Waste Supervisor (*AF*) on behalf of Edward McNulty.

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH0076	Waste Hauler Name	CHRIN HAULING, INC.
Hauler Address	1225 INDUSTRIAL DR	Vehicle License	PA-AH07880
City/State/Zip	EASTON PA 18042-6829	Vehicle VIN	1NPALU0X95N846243
Driver Name	Ryan Richard Stranzl	Vehicle Type	Rolloff Carrier,
Driver License No.	30690935	Waste Type	Municipal Waste Loose
Inspector	MICHAEL KOLESSAR	Title	ENVTL TRN
		eFACTS Client ID#	146515
Inspection Date	04/16/2025 10:15:00	No. of Viols	2
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name		Site Location	

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3
WASTE CONTAINMENT			

No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
Violations	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
Violations	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10
TRUCK/TRACTOR SIGNAGE			
No Violation	Complete business name and address sign on vehicle.	285.218(1)	11
No Violation	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13
TRAILER SIGNAGE			

No Violation	Complete business name and address sign on vehicle.	285.218(1)	14
No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
No Violation	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo #1- Leak observed on roll off container



Photo # 2- Back of vehicle



Photo #3- Damaged side of vehicle with leak observed on roll off container



Photo #4- Side of vehicle

New and Outstanding Violations

25 Pa. Code 285.213(b)(1)

Line Item: 6

Comment: Visible leaks observed on roll off container

25 Pa. Code 285.213(c)

Line Item: 7

Comment: Damaged observed on roll off

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed



Date 04/16/2025

Inspector



Date 04/16/2025

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH7358	Waste Hauler Name	DOWN 2 EARTH FARMS, LLC
Hauler Address	166 BRAINARDS RD	Vehicle License	NJ-AY524F
City/State/Zip	PHILLIPSBURG NJ 08865-9591	Vehicle VIN	1NKZXKTX9PJ258673
Driver Name	Anthony John Dasti	Vehicle Type	Rolloff Carrier,
Driver License No.	27748228	Waste Type	Municipal Waste Loose
Inspector	MICHAEL KOLESSAR	Title	ENVTL TRN
		eFACTS Client ID#	242494
Inspection Date	04/16/2025 11:25:00	No. of Viols	1
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name	Chrin Landfill	Site Location	Williams Twp

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3
WASTE CONTAINMENT			

No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
No Violation	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
No Violation	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10
TRUCK/TRACTOR SIGNAGE			
No Violation	Complete business name and address sign on vehicle.	285.218(1)	11
Violations	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13
TRAILER SIGNAGE			

No Violation	Complete business name and address sign on vehicle.	285.218(1)	14
No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
No Violation	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo #1- Side of truck. No municipal waste signage



Photo #2- Back of truck



Photo #3-Side of truck. No municipal waste signage

New and Outstanding Violations

285.218(2)

Line Item: 12

Comment: No municipal waste signage on truck

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed



Date 04/16/2025

Inspector



Date 04/16/2025

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH22546	Waste Hauler Name	HJ GENERAL CONSTRUCTION, LLC
Hauler Address	1015 BROADWAY	Vehicle License	(PA) ZTP4169
City/State/Zip	FOUNTAIN HILL PA 18015-4101	Vehicle VIN	1FDAW56P76EA28910
Driver Name	Harold M Jimenez	Vehicle Type	Truck,
Driver License No.	(PA) 32491826	Waste Type	Municipal Waste Loose
Inspector	AMY E FAULCH	Title	SLD WSTE SUPV
		eFACTS Client ID#	371747
Inspection Date	04/16/2025 08:47:59 AM	No. of Viols	2
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name	Chrin Bros. Sanitary Landfill	Site Location	Williams Township

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
Violations	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3

WASTE CONTAINMENT

No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
No Violation	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
No Violation	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10

TRUCK/TRACTOR SIGNAGE

No Violation	Complete business name and address sign on vehicle.	285.218(1)	11
Violations	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13

TRAILER SIGNAGE			
No Violation	Complete business name and address sign on vehicle.	285.218(1)	14
No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
No Violation	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo # 1: Vehicle license plate on rear of vehicle.



Photo # 2: Act 90 sticker on passenger side door.



Photo # 3: Vehicle passenger side.



Photo # 4: Vehicle driver's side.



Photo # Vehicle rear.

New and Outstanding Violations

27 P. S. 6204(f)

Line Item: 2

Comment: Act 90 written authorization card not with vehicle. Additionally, Act 90 sticker on the rear of the vehicle is incorrectly placed; this sticker should be on the driver's side door.

285.218(2)

Line Item: 12

Comment: Vehicle did not have a sign bearing the type of waste being hauled, specifically "Municipal Waste".

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed



Date

04/16/2025

Inspector



Date

04/16/2025

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH15325	Waste Hauler Name	PHILIP V. SWINT
Hauler Address	702 RIDGE ST	Vehicle License	PA-ZRT9265
City/State/Zip	BETHLEHEM PA 18015-3622	Vehicle VIN	1FDXK84P2KVA38846
Driver Name	Philip V Swint	Vehicle Type	Rolloff Carrier,
Driver License No.	20673948	Waste Type	Municipal Waste Loose
Inspector	MICHAEL KOLESSAR	Title	ENVTL TRN
		eFACTS Client ID#	155873
Inspection Date	04/16/2025 08:25:00	No. of Viols	2
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name		Site Location	

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3
WASTE CONTAINMENT			

No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
No Violation	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
No Violation	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10
TRUCK/TRACTOR SIGNAGE			
Violations	Complete business name and address sign on vehicle.	285.218(1)	11
Violations	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13
TRAILER SIGNAGE			

No Violation	Complete business name and address sign on vehicle.	285.218(1)	14
No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
No Violation	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo #1- Side of vehicle. No business name, address, or municipal waste signage



Photo #2- Back of vehicle



Photo #3- Side of vehicle. No business name, address, or municipal waste signage

New and Outstanding Violations

285.218(1)

Line Item: 11

Comment: No business name and address sign on vehicle

285.218(2)

Line Item: 12


Comment: Vehicle not marked with municipal waste signage

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed



Date

04/16/2025

Inspector



Date

04/16/2025

Municipal Waste Transporters Inspection Report

Waste Hauler ID	WH21295	Waste Hauler Name	SMALE JR ROLLOFFS
Hauler Address	90 OLEY RD	Vehicle License	ZRM5602
City/State/Zip	FLEETWOOD PA 19522-8725	Vehicle VIN	1HTSCAAL0WH539262
Driver Name	Donald C. Smale Jr	Vehicle Type	Rolloff Carrier,
Driver License No.	(PA) 24928708	Waste Type	Municipal Demo Waste
Inspector	EDWARD MCNULTY	Title	SLD WSTE SPCST
		eFACTS Client ID#	360710
Inspection Date	04/16/2025 09:35:08 AM	No. of Viols	1
Inspection Type	VEHCL - Vehicle Inspection	Inspection Result	Violation(s) Noted
Site Name		Site Location	

Check Lists

Municipal Waste Transporters (0146B)			
Status	Requirement	Chapter Citation	Line Item
WTSP AUTHORIZATION			
No Violation	Waste transporter obtained written authorization from the Department prior to operating a waste transportation vehicle.	6204(a)	1
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (cab card) and authorization stickers.	6204(f)	2
No Violation	Waste transporter operated a waste transportation vehicle with a valid written authorization (correct vehicle type).	6204(h)	3
WASTE CONTAINMENT			

No Violation	Waste is completely covered during transportation and parking with a cover that is water resistant, securely fastened, and eliminates the potential for littering, dust, leakage, discharge, vectors, and other nuisances.	285.211(a)	4
No Violation	Load compartments in collection or transportation equipment are fireproof, leak-proof and constructed to be easily cleaned.	285.213(a)(2)(i)	5
No Violation	Roll-off container is fireproof, leakproof, and constructed to be easily cleaned.	285.213(b)(1)	6
No Violation	Collection or transportation equipment tested, inspected, and maintained to ensure no release or leakage of waste.	285.213(c)	7
No Violation	Vehicle meets the specifications for transporting loose nonbaled municipal waste (four solid sides, cover in place, waste not higher than sides and all waste removed at disposal site).	285.214(b)(1)	8
No Violation	Vehicle meets the specifications for transporting baled municipal waste (bales securely fastened and covered).	285.214(b)(2)	9
No Violation	Municipal waste is transported to prevent a nuisance (dust, leaks, litter, and odor) to public health, safety or welfare.	285.215(a)	10
TRUCK/TRACTOR SIGNAGE			
No Violation	Complete business name and address sign on vehicle.	285.218(1)	11
Violations	Specific type of waste marked on vehicle.	285.218(2)	12
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	13
TRAILER SIGNAGE			

No Violation	Complete business name and address sign on vehicle.	285.218(1)	14
No Violation	Specific type of waste marked on vehicle.	285.218(2)	15
No Violation	Lettering on sign six inches in height and clearly visible and readable.	285.218(3)	16
SAFETY			
No Violation	Collection or transportation equipment is equipped with a fire extinguisher of minimum requirements.	285.213(a)(1)(i)	17
No Violation	Municipal waste is transported to prevent a hazard (overweight) to public health, safety or welfare.	285.215(a)	18
OPERATIONAL RECORD			
No Violation	Transporter maintains a daily operational record in the cab on the date of collection or transportation.	285.217(a)	19
PERMITTED FACILITY REQUIREMENTS			
No Violation	Transports municipal waste in compliance with approved facility approach routes and hours of operation.	285.215(c)	20

INSPECTION IMAGES



Photo #



Photo #



Photo #

New and Outstanding Violations

285.218(2)

Line Item: 12

Comment: Vehicle lacks signage indicating the type of waste being transported (municipal waste)

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed



Date 04/16/2025

Inspector



Date 04/16/2025

Electronic File Distribution:

Facility

Williams Township

R. Bellas/R. Miller

AQ: R. Mullin/ M. Bardzilouskas/C. Ostrowski

M. Glogowski

R. Malizia

A. Faulch

Chrin: Joseph Klobusicky

jklobusicky@chrin.org

Williams Township: Melody Ernst

mernst@williamstwp.org